

PMH HIGH PERFORMANCE



Display Operation Introduction



Key Function Instruction

3.5" Colour display



NO.	Name	Description
1	Status icon	The status of the Compressor, Fan, Timer, Running mode, Warning, Lock
2	System time	System time showing
3	Target temp	Current target temp showing
4	Inlet water temp	Inlet water temp showing
5	Outlet water temp	Outlet water temp showing
6	Power button	Power on/off and exit function

Key Function Instruction

3.5" Colour display



Mode selection



Target temp setting



One key silent mode



Timing silent setting



Error code record



Timer setting



System time setting



Parameter setting

Parameter Setting


3.5" Colour display



Upload/Download Function


Upload = parameter from PCB to Display

Download = parameter from Display to PCB



Timing Silent Function

3.5" Colour display



Timing Silent Function

3.5" Colour display



